

Island County Water Well Information



 **WellKey: FMC**

General Information

Owner Name (log): Bush Point Terrace

DOE Tag: AGA811 DOE NOI: [W100661](#)

Well Address: Dolphin Dr. Bush Pt. Road

Well Parcel:

Served Parcel:

Horiz/Vert Accuracy: GPS / DEM

Site Type: Well

DOE ID
87502

[Click to View
Well Location
in Google
Maps](#)

[Click to View
Well Location
in Google
Earth](#)

SWI Rating: Low Risk

Construction Information

Construction Date: 05/20/99

Driller Name: Well Done Drillers


LS Elevation: 127 ft. MSL

Depth Well: 150 ft.

TD Elevation: -23 ft. MSL

WL Measurements: [1 measurement \(Click to View\)](#)

WL Elevation: 5 ft. MSL



[Click to View
Scanned
Water Well
Report](#)

Water Quality Information

Water Samples: [7 samples \(Click to View\)](#)


Avg/Med/Max Arsenic: 0.005 / 0.005 / 0.005 mg/l

Avg/Med/Max Chloride: 23.41 / 23 / 26.5 mg/l

Avg/Med/Max Hardness: 195.00 / 195 / 195 mg/l

Avg/Med/Max Nitrate: 0.25 / 0.25 / 0.25 mg/l

Bacteria Samps (distribution): [292 samples \(Click to View\)](#)



[Click to View
Clicks vs EC Plot](#)

Public Water System Information

Pws Name: Bush Point Terrace Comm Club Inc.

PwsID: [09930](#)

Approved Connects: 55

Pws Source #: SO# 2


Pws Source Name: AGA811 Well 2

Water System Active Sources (SO# / SO Name)

[01 / AGA945 Well 1](#)

[02 / AGA811 Well 2](#)

[03 / Wells 1, 2 Wellfield](#)



Note: Underlined items in **bright blue** are hyperlinks to additional information / resources.
Questions? Contact the [Island County Hydrogeologist](#), or visit the [Hydrogeology Web Page](#).

Report Generated: 12/31/2020